

# ProSYN 2T

This product is not considered Hazardous according to criteria of "Worksafe Australia"

PRODUCT TYPE Two Stroke Engine Lubricating Oil

CHEMICAL DESCRIPTION Petroleum and Synthetic derived Lubricating Oil

INGREDIENTS Refined mineral and chemical additives – not hazardous

PHYSICAL DATA Flash Point C Typical > 200 C

Boiling Point >250°C Solubility in water Negligible

### FIRE AND EXPLOSION HAZARD DATA:

Flash point over 170 C. Will not burn unless heated to high temperatures.

Extinguish fires with CO2, Dry Chemical, Foam or BCF.

Fire fighters should wear self-contained breathing apparatus if fire is in poorly ventilated area and is too large for hand-held extinguisher.

### HEALTH HAZARD DATA

EYE CONTACT: May cause mild irritation SKIN CONTACT: May cause mild irritation

INHALATION: May cause mild throat or nose irritation if inhaled at elevated temperatures

SWALLOWED: May cause mild gastric irritation

# EMERGENCY AND FIRST AID PROCEDURES:

EYE CONTACT: Flush with water for 15-20 minutes

SKIN CONTACT: Wash with soap and water INHALATION: Remove to fresh air SWALLOWING: Do not induce vomiting

## IN ALL CASES SEEK MEDICAL ATTENTION IF DISCOMFORT PERSISTS

REACTIVITY DATA: INCOMPATIBILITIES: Strong oxidizers

Hazardous decomposition product Product is considered unstable

SPILL OR LEAK PROCEDURE Contain spill and shut off all sources of possible ignition

Absorb on fire retardant material, sand or earth.
Follow State or Local Authority regulations for disposal.

### STORAGE AND HANDLING PROCEDURE

Not defined as Dangerous Goods for transport by road or rail.

Store away from heat, oxidizing agents, foodstuffs and clothing. No health risks are expected as a result of normal handling.

REFFERENCE: FOR INFORMATION CONTACT:

ISSUE DATE: Synforce (Aust.) Pty Ltd, P.O. Box 7181, Urangan, Hervey Bay, QLD. 4655

February 2021 Telephone 07-41253531 Fax 07-41253521

Where the information provided in this bulletin indicates a potential hazard, adequate warning should be given to all

